

Voltage detectors

Voltage detectors accessories

Insulation tester

Installation testers identifier

Multimeter clamp-meter

Infrared Thermometer

## Digital multimeter- Cat III 600 V

This digital multimeter is compact 3 1/2 digit. For measuring DC and AC voltage and current, resistance, continuity and temperature.

- AC frequency response: 40 - 400 HZ
- DC voltage: 200 mV/2 V/20 V/200 V/600 V
- AC voltage: 200 mV/2 V/20 V/200 V/600 V
- DC current: 200  $\mu$ A/2000  $\mu$ A/200 mA/2 A/10 A
- AC current: 200  $\mu$ A/2000  $\mu$ A/200 mA/2 A/10 A
- Resistance: 200  $\Omega$ /2 k $\Omega$ /20 k $\Omega$ / 200 k $\Omega$ /2 M $\Omega$ /20 M $\Omega$
- Capacitance: 20  $\mu$ F 200  $\mu$ F/2  $\mu$ F/200  $\mu$ F/1000  $\mu$ F

### General specifications

- 3 1/2 digital multimeter, 30 ranges, 70 x 50 mm LCD display, 1999 counts max.
- Back light, data hold
- Diode, triode performance testing, continuity test (audible)

### General characteristics

- Battery: 3 x 1.5 V AAA batteries
- Low battery indication level on LCD
- Operation temperature: 0°C / 40°C, < 75%RH
- Storage temperature: -10°C / 50°C, < 85%RH



**MX-701** 158 x 75 x 35 mm - Weight: 200 g

CE

## Digital clamp meter - Cat III 600 V

This digital clamp meter is compact 3 1/2 digit. Autorange for measuring DC and AC voltage, AC current, resistance, diode, continuity and temperature.

- AC current: 2 A - 600 A.
- AC voltage: 2 V - 600 V. DC voltage: 0.2 V - 600 V.
- Resistance: 200  $\Omega$  - 20 M $\Omega$ . Continuity: buzzer (< 50  $\Omega$ ).
- Temperature range: -40°C/+1000°C -40°F/-1832°F.

### General specifications

- Display: 3 1/2 digit LCD with a max. reading of 1999
- Polarity: auto polarity indication
- Overrange indication: "OL" or "-OL"
- Automatic zeroing function
- Sensor: clamp-shape transformer for AC measurement
- Jaw opening capability:  $\varnothing$  36 mm
- Max. measurable conductor:  $\varnothing$  30 mm

### General characteristics

- Battery: 2 x 1.5 V AAA batteries
- Low battery indication
- Operation temperature: 0°C / 40°C, < 75% RH
- Storage temperature: -20°C / 60°C, < 85% RH

**MX-702** 190 x 70 x 38 mm - Weight: 220 g



CE

## POINTEST™ Safety test probes for multimeter and clamp-meter

Safety test probes for multimeter and clamp-meter use only. 4 mm retractable shrouded plugs, 4 mm standard socket or 1.20 m double sheathed lead. Probes 26 mm length, 1 000 V A.C or D.C, IP2X.

**DX-02001** Set of 2 contact probes, black and red with socket

**DX-02002** Set of 2 contact probes, black and red 1.20 m lead



LOW VOLTAGE